

Name Sean Clarke.....

ParishHighmoor.....

Date of report 2nd April 2024

PATH NUMBER	PATH TYPE (footpath, bridleway, Restricted byway)	GRID REFERENCE*	COMMENTS/ACTION REQUIRED	ACTION TAKEN	LANDOWNER DETAILS (if known)	DATE OF INSPECTION
249/1	Footpath	SU701 856	Building site fence crosses footpath	Reported July 22 CAMs Web:PROW 220714649		08/12/23
249/2	Footpath	NA	Inspected - clear	NA	NA	25/02/24
249/3	Footpath	SU700 851	Inspected - Stile is of poor design and poor state of repair. It does not match OCC recommendations	Reported on OCC website Ref 240414626	NA	25/02/24
249/4	Footpath	NA	Inspected - clear	NA	NA	02/04/24
249/5	Footpath	NA	Inspected - clear	NA	NA	02/04/24
249/6	Footpath	NA	Inspected - clear	NA	NA	25/02/24
249/7	Footpath	NA	Inspected - clear	NA	NA	27/11/23
249/8	Footpath	NA	Inspected - clear	NA	NA	21/03/24
249/9	Footpath	NA	Inspected - clear	NA	NA	21/03/24
249/10	Footpath	NA	Inspected - clear	NA	NA	27/11/23
249/11	Footpath	NA	Inspected - clear	NA	NA	21/03/24
249/12	Bridleway	NA	Inspected - clear	NA	NA	21/03/24
249/13	Bridleway	NA	Inspected - clear	NA	NA	21/03/24
249/14	Bridleway	NA	Inspected - clear	NA	NA	21/03/24

249/15	Footpath	NA	Inspected - clear	NA	NA	02/04/24
249/16	Footpath	NA	Inspected - clear	NA	NA	02/04/24
249/17	Footpath	NA	Inspected - clear	NA	NA	21/03/24
249/18	Footpath	NA	Inspected - clear	NA	NA	02/04/24
249/19	Footpath	NA	Inspected - clear	NA	NA	21/03/24
249/20	Footpath	NA	Inspected - clear	NA	NA	21/03/24
249/21	Bridleway	NA	Inspected - clear	NA	NA	21/03/24
249/22	Footpath	NA	Inspected - clear	NA	NA	21/03/24
249/23	Footpath	NA	Inspected - clear	NA	NA	21/03/24
249/24	Res Bridle	NA	Inspected - clear	NA	NA	25/02/24
249/25	Bridleway	SU706 846	Section overgrown with rhododendrons	On hold. Nettlebed Estate would rather we held off from cutting back the rhododendrons until after they've flowered.	NA	02/04/24
249/26	Bridleway	NA	Inspected - clear	NA	NA	02/04/24
249/27	Footpath	NA	Inspected - clear	NA	NA	02/04/24
249/28	Bridleway	NA	Inspected - clear	NA	NA	10/01/24
249/29	Bridleway	NA	Inspected - clear	NA	NA	10/01/23
241/30	Bridleway	NA	Inspected - clear	NA	NA	02/04/24
249/31	Footpath	NA	Inspected - clear	NA	NA	02/04/24
249/32	Footpath	SU703 840	Dead tree fallen across path	Reported to Chiltern volunteers	NA	02/04/24
249/33	Footpath	NA	Inspected - clear	NA	NA	30/01/24
249/34	Footpath	NA	Inspected - clear	NA	NA	21/03/24
249/35	Footpath	NA	Inspected - clear	NA	NA	21/03/24

- Ideally grid references should be two letters and eight figures. There are free grid reference finder apps on smart phones, which are quick and easy to use.

Summary

The paths are in good order although very muddy in places following a very wet winter.

The parish has been supported by two Chiltern Society working parties and help from OCC and landowners.

I have continued with path clearing, sign replacements and refreshing arrows on trees

We have had a 6 of trees down all of which have been cleared. One more is awaiting removal

3 Way marker posts and been replaced.

At the request of the Nettlebed Estate we have tried to better define the routes of HM18 and HM33.